

ABTW_0068 - B787 Servicing and Safety Answer Key

B787 Aircraft Service and Safety Review

Ramp agents must follow the direction of the WestJet AME during the B787 turn and assist as necessary.

- ☒ True
☐ False

B787 Aircraft Service and Safety Review

How many ground power cables must be connected to the B787 for normal turns?
Select ALL correct answers.

- ☐ One
☒ One, if only one is available.
☒ Two
☐ Three

B787 Aircraft Service and Safety Review

Cable support lanyards are required for GPU cables **unless** the AME deems them unnecessary.

- ☐ True
☒ False

B787 Aircraft Service and Safety Review

Never disconnect ground power without approval from the:

type your text here

Answers may include (not case sensitive): **flight deck, captain, PIC, pilot, pilots, flight crew**

ABTW_0068 - B787 Servicing and Safety
Answer Key

B787 Aircraft Service and Safety Review

If only one cargo loader is being used for the flight, which hold must be offloaded first?

- ☐ The forward hold
- ☒ The aft hold
- ☐ The bulk hold

B787 Aircraft Service and Safety Review

Ground power must not be used during lightning alerts.

- ☒ True
- ☐ False