

ABTW_0069 - B787 Lav and Water Servicing Answer Key

Lavatory Service Review

The B787's lavatory tanks must be filled simultaneously to maintain weight and balance of the aircraft and to prevent tail-tips.

- ☐ True
- ☒ False

The **RINSE** and **FILL** amounts for B787 lavatory service are:

- ☐ 1,628 L (430 US gal.) rinse / 95 L (25 US gal.) fill for each tank.
- ☐ 430 L (114 US gal.) rinse / 95 L (25 US gal.) fill for each tank.
- ☐ 95 L (25 US gal.) rinse / 38 L (10 US gal.) fill for each tank.
- ☒ 38 L (10 US gal.) rinse / 38 L (10 US gal.) fill for each tank.

Water Service Review

The UV DELAY light on the water service panel means that the UV filter system is warming up prior to service.

- ☒ True
- ☐ False

Water Service Review

What happens if the FLIGHT button is not pressed when water servicing has been completed?

- ☐ Water will leak from the system.
- ☐ The UV disinfection system will not function.
- ☐ The potable water system will cease functioning until the APU or GPU are restarted.
- ☒ The cabin will be without water until after takeoff.